



The dips pointed to in green arrows are a result of the temperature going up (temperature graph would be inverted from the yellow) from the signal drop, which means the scan passes through the absorption dip again.

These signals are not well-resolved since the response time causes the absorption dips to start overlapping. They were not included in the analysis.

